




# CHECK MASTER



6882-600A



horizontal orientation



vertical orientation

- To check the accuracy of table movement of machine tools, to calibrate height gauges and CMMs
- Ceramic gauge blocks
- Can be used in either vertical and horizontal orientation
- Supplied with inspection certificate

(mm)

Code	Range	Step	Accuracy	Parallelism of blocks	L	L1	H	W
6882-300A	300mm	10mm	$\pm 2.5\mu\text{m}$	1.2 $\mu\text{m}$	350	310	49	45
6882-450A	450mm	10mm	$\pm 3.5\mu\text{m}$	1.5 $\mu\text{m}$	510	470	54	50
6882-600A	600mm	10mm	$\pm 3.5\mu\text{m}$	1.5 $\mu\text{m}$	650	610	54	50